	_	
Submit 3 Copies To Appropriate District	te of New Mexico	Form C-103
Officenergy Mir	nerals and Natural Resources	Revised March 25, 1999
Distric 1 1625 N. French Dr., Hobbs, NM 87240		WELL API NO.
District II OIL CON	SERVATION DIVISION	30-015- 2(152
811 South First, Artesia, NM 87210  District III  2040 South Pacheco		5. Indicate Type of Lease
TOOO DI	nta Fe, NM 87505	STATE   FEE 🔀
District 1 V	nta re, inivi 87303	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505		
SUNDRY NOTICES AND REPOR		7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)		Rear
1. Type of Well:		
Oil Well Gas Well A Other		O W-UNI
2. Name of Operator	16696	8. Well No.
OXY USA Inc.	10090	9. Pool name or Wildcat
3. Address of Operator P.O. BOX 50250 MIDLAND, TX 79710-0250		Carlsbad Stoawn, South
4. Well Location		On 18100 History Dutes
4. Wen Education		
Unit Letter J: 1650 feet from the South line and 1980 feet from the East line		
	hip ZZS Range ZZE	NMPM EDDY County
10. Elevation (	Show whether DR, RKB, RT, GR, e	tc.)
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO	I	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABA	NDON 🔲 REMEDIAL WO	RK ALTERING CASING
TEMPORARILY ABANDON		RILLING OPNS. PLUG AND
D OD ALEED GAGNIG		ADANDONMENT
PULL OR ALTER CASING	CASING TEST A	
COMPLETION	CEMENT 30B	un en
OTHER:	OTHER:	
12. Describe proposed or completed operations. (Cl	early state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 110	3. For Multiple Completions: Atta	ch wellbore diagram of proposed completion
or recompilation.	~	• •
<u>.</u>		
		•
		<b>*</b>
500 0	ther side	
JEE 0	the stee	55 16 A V C
<b>\</b>	_	3 76 06 31 m
<i>*</i> 1	-	All the state of t
<b>\'</b>		
200	-	
<b>6</b>		
40		
I hereby certify that the information above is true and	complete to the best of my knowle	edge and belief
Thereby certify that the information above is true and	2 complete to the best of my mis with	
SIGNATURE L	TITLE REGULATORY	Y ANALYST DATE 8/21/00
Type or print name DAVID STEWART		Telephone No. 915-685-5717
(This space for State use)		
(This space for State use)	<i>4 1</i> 3	, a FEB 12 200
APPPROVED BY	TITLE 5	DATE
Conditions of approval, if any:		1340
••		Y -

OXY USA INC. BEAR #1 SEC 17 T22S R27E EDDY CTY, NM

NOTIFY NMOCD OF INTENT TO P&A. MIRU PU 5/15/00, KILL WELL, ND WH, NU BOP. CIRC W/ 10# BW, REL PKR & POOH W/ PKR & TBG. RIH & SET CIBP @ 10114', CIRC w/ 10# MLF, SPOT 25sx CL H CMT TO 9994', POOH. SPOT 25sx CL H CMT FROM 9466-9346', POOH W/ TBG, RD BOP & WH. RIH & STRETCH CSG, 7" CSG FREE @ 5175', NOTIFY NMOCD, PERF & SQZ @ 6980'. RIH & PERF 4SPF @ 6980'. RIH W/ PKR, UNABLE TO GET PAST 1200', REC NMOCD APPROVAL TO SPOT 50sx CL C CMT FROM 7030-6718', WOC, SION. RIH & TAG CMT @ 6805'. RIH & CUT 7" CSG @ 5425', RU CSG JACKS & ATTEMPT TO PULL CSG, PARTED 3' BELOW SURFACE, ND WH, NU BOP. NOTIFY NMOCD, REC AMENDED PLUGGING PROCEDURE. RIH W/ TBG TO 5481', BREAK CIRC, SET PKR @ 1134', SPOT 50sx CL C CMT FROM 5481-5169', POOH, WOC, SION. RIH & TAG PLUG @ 5260'. PERF @ 3875', EIR @ 2BPM @ 0#, CMT SQZ CSG @ 3875' W/ 50sx CL C CMT, DISPL TO 3613', POOH W/ 10jts TBG, WOC, SION. RIH & TAG PLUG @ 3705'. PERF @ 1850', UNABLE TO PUMP INTO PERFS & OUT 9-5/8" CSG @ 700#. PERF @ 1775', UNABLE TO PUMP INTO PERFS & OUT 9-5/8" CSG, REC NMOCD APPROVAL, SPOT 35sx CL C CMT FROM 1900-1686', POOH. RIH & PERF 404', CMT SQZ W/ 80sx CL C CMT'W/ 2% CaCl<sub>2</sub>, WOC-3hrs. RIH, NO TAG, SPOT 80sx CL C CMT @ 451', WOC, SION. RIH & TAG PLUG @ 200', REC NMOCD APPR & SPOT 20sx SURFACE PLUG. RDPU 6/7/00, DUG OUT CELLAR, CUT OFF WH & ANCHORS, INSTALL DRY HOLE MARKER, CLEAN