

WELL WORK REPORT

Page 7 of _____

Lease Name WOOD CANYON UNIT #1

Well Number _____

Location _____

Elevation _____ Perm. Datum _____

Down Hole
Condition
(after work)

Reason for Work _____

Date	Operation
7-2-74	Drlg. @ 4010'. Lm. and Sh. (+375'). Deviation $3/4^{\circ}$ - 3940. Drlg w/fresh water. 20'/hr.
7-3-74	Drlg @ 4450. (+440'). Bit #7. Mixed 20 sacks Lime. Deviation $3/4^{\circ}$ @ 4440.
7-4-74	Drlg @ 4810. Fresh Water and Lime, Mud. \$243 for water and \$63.50 for Lime.
7-5-74	Drlg @ 5260. Deviation $3/4^{\circ}$ @ 4945. Drlg. w/ fresh water and Lime. \$112.20 water cost last 24 hrs. Mud cost \$63.60. MCTD \$222.45.
7-6-74	Drilled to 5387. Lost two jets and bit locked up. Now make trip with magnetic basket. Water cost \$112.20. Mud cost \$31.75. MCTD \$254.20.
7-7-74	Drlg @ 5765. Bit #8 Reed FP-63. Deviation $1\frac{1}{4}^{\circ}$ @ 5387. Water cost \$0. Mud cost \$9.30. MCTD \$263.50.
7-8-74	Drlg @ 6170'. Water cost \$398.80. Mud cost \$9.30. MCTD \$272.80.
7-9-74	Drlg @ 6580. Deviation $1\frac{1}{2}^{\circ}$ @ 6345. Water cost \$0. Mud cost \$9.80. MCTD \$282.10.
7-10-74	Drlg. @ 6910. Sh (+330). Deviation $1\frac{1}{2}^{\circ}$ @ 6848. Water cost \$268.20. Mud cost \$9.30. MCTD \$291.40.
7-11-74	Drlg. @ 7250. Lm & Sh (+340). Water cost \$210.60. Mud cost \$87.30. MCTD \$378.70. (Lost 140 bbls mud last 24 hrs., seepage, mixed 12 bags paper.)
7-12-74	Drlg. @ 7590. Water cost \$102.00. Mud cost \$92.10. MCTD \$470.80.
7-13-74	Drlg @ 7990. Bit #8 in hole. Water cost \$186. Mud cost \$88.10. MCTD \$558.90. (Lost 30 bbls mud on morning tower. Mixed 8 bags paper Ok now.)
7-14-74	Drlg @ 8350. Deviation $1\frac{1}{4}^{\circ}$ @ 8348. Water

Signed _____