

Daily Report

Workover & Recomplete in Morrow Sands

Cueva Unit #1
Sec. 6-T23S-R26E
Sheep Draw Field
Eddy County, New Mexico

4/23/96 7:40AM 830 psi.
7:50AM put on pipeline with 5/64 choke, sold 1 hour
still had 670 psi. stopped selling and blew
down, started swabbing.
1 run fluid level 4500'
2 run fluid level 5100' no go swab cups & jars
stayed in hole.
Pride went in with sinker bar and touched the jars
on the PF nipple.
Jars, cups & no go still on PF nipple.
4 run fluid level 5100' went to 6300'
5 run fluid level 6300' went to 8000'
6 run fluid level 6900' went to 8400'
7 run fluid level 7500' went to 9100'
8 run fluid level 9100' went to 10,500'
9 run fluid level 10,000' went to 11,140'
PF nipple
3:20PM went in hole w/overshot 1 3/8" tool
lower socket slip. 1 5/8" jars looking up.
10 run fluid level 9600' went to 11000'
4:30PM shut in.

4/24/96 7:30AM 15 hour buildup 740 psi put on pipeline sold
1 hr.
8:40AM
1 run fluid level 4500'
2 run fluid level 5700'
3 run fluid level 6300'
4 run fluid level 7500'
5 run fluid level 8000'
6 run fluid level 9100'
7 run fluid level 10,000' PF nipple
8 run dry fish run, tried to fish no go, cups &
jars, crew tried to use same tools as on
4/23/96. could not get down below 1000' to
1200'
1:06PM down, cut and repair swab line.
2:55PM Picked up swab lubricator to start swabbing.
3:17PM
8 run fluid level 6900', could not go down,
came out, changed cups.
3:40PM swab line had to repair again.
4:35PM put to pipeline.