

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

NOV 20 1978

O. C. C.
ARTEBIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4541
7. Unit Agreement Name
8. Farm or Lease Name Sulphate Aunt
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Eddy

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Corinne Grace ✓	
3. Address of Operator P. O. Box 1418, Carlsbad, New Mexico 88220	
4. Location of Well UNIT LETTER <u>C</u> <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>3</u> TOWNSHIP <u>24S</u> RANGE <u>27E</u> NMPM.	
15. Elevation (Show whether DF, RT, CR, etc.) 3173.2	

<p align="center">16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p align="center">NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/></p>	<p align="center">SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-9-78 Plugged and abandoned as follows:

Ran tubing to T.D. loaded with mud. Set 100 sacks of "C"-Plug from 1050' to 1200'
 100 sxs of class "C" " 300' to 450'
 20 sxs of Class "C" " 0' to 20'

Pulled 16" casing

Dry hole marker set.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Heanite Jones Wildberger TITLE Agent DATE 11/16/78

APPROVED BY Mike Sturges TITLE OIL AND GAS INSPECTOR DATE OCT 17 1979

CONDITIONS OF APPROVAL, IF ANY: