

Intermediate

**Dark Canyon #1
January 1997 Plug Back to the Strawn
Morning Report**

needed. The tank was repaired.

Discussion - Gas Meter: Highland will change out the meter plate tomorrow to a 1" plate

2/22 Sat 200 MCF/D, 1000 psi shut in pressure, choke froze off, relief valve on facilities popped off.

2/23 Sun 200 MCF/D, Freezing Problems

2/24 Mon Shut well in; Waiting of Natco

Discussion Facilities: Natco will be out Monday to go through the 250,000 BTU/hr stack pack and recommend anything that needs to be repaired in order to fire the vessel. At the very least, the air actuated choke needs to be replaced. This facility is in marginal condition and may be too small. Once Natco has made their recommendation, a decision will be made whether or not to replace the unit.

Attempting to flow the well with the wellhead choke at higher rates will not be attempted because of the safety issues. There is no expansion line in the flowline and the risk of a flowline part is not warranted.

3/3 Mon Natco has parts will start on stack pack 3/4

Discussion - Material Transfers:

Description:	One 1-1/4" x 14' pony, 173 7/8" rods, 260 3/4" rods.
From:	Dark Canyon #1
To:	ACU #406
Condition:	Used
Price:	\$2032.90
Basis:	Market Price Quote #1 (High Quote): Rod Tec., Inc. Levelland, Texas \$0.24/ft. for 1", \$0.33/ft. for 1-1/4", \$0.24/ft. for 7/8", \$0.24/ft. for 3/4", total \$2607.90, minus trucking \$575.00.

Mineral Technologies, Inc.
Engineering consultants
Operator
January 28, 1997