

START CHART #2

Waiting on rig.

Test #11 Repeated test. Pressured to 300# with leak to rod
packing of pipe rams bop (doghouse side). Tightened.

Test #12 Repeated test. Pressured to 3000# with leak to rod
packing of blind rams bop (pipe rack side); repressured
to 3000# with same leak. DISCONTINUED TESTING AS DESIRED
AT THIS TIME.

YELLOW JACKET TOOLS AND SERVICES, INC.

ODESSA, TEXAS

Test made by Billy Lee *Billy Lee*