

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.C.S.	2
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 9 1975

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

30-015-21476

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

**SUNDY NOTICES AND REPORTS ON WELLIESIA, OFFICE**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Belco Petroleum Corporation ✓	8. Farm or Lease Name Martin Com
3. Address of Operator 411 Petroleum Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> <u>2198</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>22-S</u> RANGE <u>27-E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated South Carlsbad Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3136.5' GL	12. County Eddy

**Check Appropriate Box To Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Amended Location

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was originally staked 1980' FNL and 1650' FWL of Section 20. However, due to a 6' deep concrete irrigation ditch 20' north of the proposed wellsite, it was necessary to move the location 218' due south. It would have been impossible to drill a well at the location without damaging the land owner's irrigation system. Also, the land owner was intending to use the irrigation system in the immediate future. Attached is a plat showing the actual location where the well was drilled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. T. Horton, Jr. TITLE Operations Engineer DATE 6/6/75

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUN 9 1975

CONDITIONS OF APPROVAL, IF ANY: