

CASING PROGRAM

Lease:

Well No.:

Intermediate - Drill a 12 1/4" hole to 2500'+ and set 8 5/8" casing.

PIPE REQUIREMENT				
<u>AMOUNT</u>	<u>SIZE</u>	<u>WT./FT.</u>	<u>GRADE</u>	<u>CONNECTION</u>
<u>1800'</u>	<u>8 5/8"</u>	<u>24.0</u>	<u>K-55</u>	<u>ST&C</u>
<u>700'</u>	<u>8 5/8"</u>	<u>32.0</u>	<u>K-55</u>	<u>ST&C</u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

CASING EQUIPMENT & PREPARATION

Run casing with a guide shoe, insert float with automatic fill, three centralizers, and 2 pounds thread compound.

Sandblast bottom 500 feet and clean threads.

CEMENT PROGRAM

Stage No.	Type & Additive Composition	Sl. WT. #/gal.	Sl. VOL. ft. ³ /sx.	Water gal./sx.	Pump Time	24 hr. Comp. St. psi @ degrees
950	Halliburton Light 5# Gilsonite 1/4# Floccle	12.2	2.04	11.2	4:00+	225 @ 110
200	Class C 2% CaCl	14.8	1.32	6.3	1:50	2680 @ 110

Remarks: