

Form 9-331
Dec. 1973Form Approved.
Budget Bulletin 10-1-74 424UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen wells in a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐ MAY 12 1980
2. NAME OF OPERATOR
Amoco Production Company
3. ADDRESS OF OPERATOR
P. O. Box 68 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit B, NW/4, NE/4) Sec. 19
AT TOP PROD. INTERVAL: 660' FNL X 1980 FEL
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE
NM-0415461
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
C. D.
ARTESIA, OFFICE
8. FARM OR LEASE NAME
Old Indian Draw Unit
9. WELL NO.
3
10. FIELD OR WILDCAT NAME
Indian Draw - Delaware
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
19-22-28
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3073.7

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to increase production by the following method:

Run tubing and packer and set packer at 3150' with 30' of tailpipe.
Acidize delaware perfs (3298'-3318') with 1000 gallons 15% HCL acid,
2000 gallons 12-3% ACID, AND 1000 gallons 2% NH4 Cl. Flush with
15 bbls. brine water. Return well to production.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED George H. Stewart TITLE Asst. Admin. Analyst DATE 5-9-80

(This space for Federal or State office use)

APPROVED BY GEORGE H. STEWART

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DISTRICT ENGINEER

DATE MAY 12 1980

0+4-USGS, A

1-Hou

1-Susp

1-MKE