

untagged lease water. Run gamma ray temperature log from 3380'-3180'. If there is no channeling below 3330' return well to production. If a channel is indicated acidize with 1900 gallons 15% HCL, 3800 gallons 12% HCL-3% HF, and 1250 gallons 2% NH4CL tagged with 1 MC/1000 Iodine-131. Flush with 600 gallons lease water. Run gamma ray temperature log from 3380'-3180'. Swab back load. Pull workstring and packer. Run production equipment and return well to production.