Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, ...ii...als and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION P.O. Box 2088

5.	Indicate Type of Lease	
	3 0-015-21551	
4 E	LL AT NO.	

DISTRICT II	Conto En Mass Massias	00 87,50 4,2 70,58	30-015-21551			
P.O. Drawer DD, Artesia, NM 88210	Salita re, New Mexico		5. Indicate Type of Lease STATE	FEE X		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		NOV 1 4 1991	6. State Oil & Gas Lease No.	FEE (A)		
DIFFERENT RESERV (FORM C-10	ES AND REPORTS ON WEI POSALS TO DRILL OR TO DEEPEN POIR. USE "APPLICATION FOR PE OI) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Nam	TIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII		
1. Type of Well: OIL GAS WELL WELL X	OTHER		Mary K. Knobel			
2. Name of Operator	nony (HSA) /		8. Well No.			
Pacific Enterprises Oil com 3. Address of Operator 4245 Kemp, Suite 600, Wichi			9. Pool name or Wildcat Carlsbad South (Strawn)			
4. Well Location						
Unit Letter : 1980	Feet From The	Line and	980 East Feet From The	Line		
Section 32	Township 22M Ra	ange 27E	NMPM Eddy	County		
	10. Elevation (Show whether 3162 GR	DF, RKB, RT, GR, etc.)				
	ppropriate Box to Indicate		•			
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASIN	1G		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GIOPNS. PLUGIAND ABAN	IDONMENT X		
PULL OR ALTER CASING CASING TEST AND CEMENT JOB						
OTHER:		OTHER:	·	🗆		
12. Describe Proposed or Completed Operation work) SEE RULE 1103.	ns (Clearly state all pertinent details, ar	nd give pertinent dates, inclu	ding estimated date of starting any propos	æd		
10-29-91: ND tree, NU BOP's. 10-30-91: Rel Lok-set pkr @ 1 & Strawn.			ne wtr & TOH. Spot 75 sx CL "H" cmt acro	ss Atoka		
10-31-91: Tagged cmt plug @ 1 11-01-91: TIH w/2 3/8" tbg, s	set ret @ 5533'. Est circ	to 4 1/2"-9 5/8" ar	Plug f/8246'-8922'. Perf @ 5 nnulus. Load annulus w/200	700'. BLWTR		
<pre>& pmp'd 75 sx CL "C" neat, dumped 35' cmt on cmt retainer. 11-02-91: TOOH w/2 3/8" tbg, perf @ 2100' (4 holes). Set cmt ret @ 1690', circ 200 sx CL "C" neat up 4 1/2"-9 5/8" annulus. Dump 35' cmt on ret. Perf @ 400' (4 holes). Pmp 130 sx CL "C" neat dn 4 1/2", up 4 1/2"-9 5/8" annulus, bullheaded 135 sx CL "C" neat dn 9 5/8" -13 3/8" annulus.</pre>						
Weld on dry hole ma	arker, set in cmt. Gary Williams of the New N	Mexico OCD.	Post 1 12 - 6	[D-2 6-91		
. a A withoused by	22.,		P+A			
I hereby certify that the information above is true an			gineering Manager 11/0	08/91		
SIGNATURE A MAN Smith	π		DATE	(817) 692-300		
TYPEOR PRINT NAME Stan M. Smith			TELEPHONE NO.			
(This space for State Use)		4-12 N	111	ela es		

CONDITIONS OF APPROVAL, IF ANY: