

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21599
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Forehand
8. Well No. #1
9. Pool name, or Wildcat Cass Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	
4. Well Location Unit Letter <u>K</u> : <u>1980'</u> Feet From The <u>South</u> Line and <u>1980'</u> Feet From The <u>West</u> Line Section <u>15</u> Township <u>23S</u> Range <u>27E</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3127 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Plugback & Test Bone Springs <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/12/90 Set CIBP @ 11,750' w/35' cmt on top
1/14/90 Spot 100' plug from 11,528-11,420'
Spot 100' plug from 10,472-10,372'
Set CIBP @ 8975; Tag top of cmt @ 8934'
1/17/90 Sqz perms 8602-94'; Tag TOC @ 8922' (PBTD)
1/20/90 Perf 8642.5-8857 (OA); Acdz w/4000 gals 7 1/2%
Frac w/54,500 gals DS-45 + 80,250# 16/20 carbolite
2/1/90 Put on production

RECEIVED

JUL 27 '90

ARTESIA, OFFICE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tim W. Gum TITLE Engineer DATE 7/25/90
TYPE OR PRINT NAME Tim Gum TELEPHONE NO. 623-6601

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ DATE AUG 10 1990

CONDITIONS OF APPROVAL, IF ANY: