

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1001-01-3
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 67103

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

The Eastland Oil Company

RECEIVED

3. ADDRESS OF OPERATOR

P. O. Drawer 3488, Midland, Texas 79702

OCT 03 '88

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1380' FSL & 990' FEL

O. C. D.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

Laguna Grande Unit

8. FARM OR LEASE NAME

Laguna Grande Unit (Fed)

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat (Bone Springs)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 28, T-23-S, R-29-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3003 GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Install Plunger Lift Pump

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to move in Wireline unit & Broach 2 7/8" tubing. Set landing nipple, tubing stop, Subsurface Bumper, & run 2 7/8" plunger. Hook up and tie in surface equipment, and start producing.

Propose to do this approximately 9/29/88.

RECEIVED
SEP 27 11 33 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED Travis Reed

TITLE Production Superintendent

DATE 9/26/88

(This space for Federal or State office use)

APPROVED BY ONLY MINERAL RESOURCES

TITLE _____

DATE 9-29-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side