

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved
Budget Project No. 42-R1421.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-330
2. NAME OF OPERATOR Gulf Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 670, Hobbs, NM 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FNL & 1980' FEL		8. FARM OR LEASE NAME Franklin et al Federal
14. PERMIT NO.		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RL, GS, etc.) 3973' GL		10. FIELD AND POOL, OR WILDCAT Strawn
		11. SEC., T., R., M., OR BLM, AND SURVEY OR AREA 24
		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) P&A	X		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

POH with production equipment. Set CIBP at 8400', cap with 50' cement. Load hole back to 6800' with abandonment mud. Spot 75' cement inside cut-off point of casing and 75' above. Circulate abandonment mud back to surface. Spot 150' cement 5500'-5350'; spot 100' plug 4050'-3950'; spot 100' cement 2650'-2550'. Spot 25 sack surface plug. Place dry hole marker, clean and clear location.

RECEIVED

JAN 09 1981

O. C. D.
ARTEZIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED P. D. Pite	TITLE Area Engineer	DATE 1-7-81
(This space for Federal or State office use)		
APPROVED BY (Orig. Sgd.) PETER W. CHESTER	TITLE ACTING DISTRICT ENGINEER	DATE JAN 8 1981
CONDITIONS OF APPROVAL, IF ANY:		