

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
JAN 31 1977
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole		7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation		8. Farm or Lease Name Fee "76"
3. Address of Operator P.O. Box 848, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT CENTER F 2310' FEET FROM THE North LINE AND 1650' FEET FROM West LINE, SECTION 9 TOWNSHIP 24-S RANGE 27-E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3152' G.I. 3153' D.F.		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REEL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

As per verbal instructions 1/24/77, it is proposed to plug and abandon this test as follows:

100' cement plugs--2050-2150 (T.Delaware sand), 1750-1850 (B.Salt),
 1150-1250'(T.Salt), 300-400'(Stub of 8 5/8"csg.) 10 sx plug at surface.
 Install dry hole marker, and restore surface, as near as possible, to
 it's original condition.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack J. McClellan TITLE Operator DATE 1/24/77

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JAN 31 1977

CONDITIONS OF APPROVAL, IF ANY: