

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO ABANDON OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO ABANDON" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name <u>OLD INDIAN DRAW UNIT</u>
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>		8. Farm or Lease Name <u>OLD INDIAN DRAW UNIT</u>
3. Address of Operator <u>P.O. DRAWER A, LEVELLAND, TEXAS, 79336</u>		9. Well No. <u>24</u>
4. Location of Well UNIT LETTER <u>J</u> <u>1659</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>2257</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>7</u> TOWNSHIP <u>22-S</u> RANGE <u>28-E</u> NMPM.		10. Field and Pool, or Wildcat <u>INDIAN DRAW DELAWARE</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3086.6 GR</u>		12. County <u>EDDY</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

REACH TD OF 3450 4:15 PM 6-16-77. RAN LOGS AND SIDEWALL CORES.
RAN 5 1/2" CASING AND SET AT 3450. CEMENT WITH 485 SX INCOR WITH
ECONOLITE AND 7 1/2 # SALT, 10 # GILSONITE AND 1/4 # FLOCELE/SX, FOLLOW WITH 100 SX
50-50 POZ MIX WITH 2 % CACL. PLUG DOWN AT 10:00 PM 6-17-77, CIRCULATE
30 SX. RIB RELEASED 12:00 PM 6-17-77. MOVE IN SERVICE UNIT 6-19-77. WOC 50 HR,
TEST CASING WITH 3100 # FOR 30 MIN. TEST OK. RAN GAMMA RAY CORRELATION LOG 3000-3414.
PERF DELAWARE 3298-3328 WITH 20PTSPP, RAN TBG AND SPOT 1 BBL 7 1/2 %
CLAY STABILIZING ACID WITH ADDITIVES ACROSS PERFS, WASH AND SOAK. ACIDIZE
PERFS WITH 3000 GAL 7 1/2 % CLAY STABILIZING ACID, SWB TEST AND EVALUATE.
INSTALL PUMPING EQUIPMENT 6-22-77. TEST WELL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Kenneth Brand</u>	TITLE <u>Senior Staff Assistant</u>	DATE <u>6-30-77</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>JUL 5 1977</u>
CONDITIONS OF APPROVAL, IF ANY <u>0+4 NMOC, ART 1-DIV, 1-KWB, 1-MARATHON, 2-BASS</u>		