

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED

JUL 12 1977

O.C.C.

ARTESIA, OFFICE

SUNDY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator C. E. LaRue and B. N. Muncy, Jr.
3. Address of Operator P.O. Box 196 Artesia, NM 88210
4. Location of Well UNIT LETTER J, 1750 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 8 TOWNSHIP 23 S RANGE 28 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3017.1

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Term of Lease Time ONSUREZ
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>
OTHER <input type="checkbox"/>	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMERCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed to Plug and Abandon by setting 35 sacks of cement, Plug At 3347-3447, 35 sacks of cement Plug at 2401-2507, 35 sacks of cement Plug at 1760-1860 at Base of Salt, 35 sacks of cement Plug at 419-519 at Casing Shoe, 10 sacks of cement Plug at Surface, with Heavy Mud Between All Plugs.

Set Dry Hole Marker, Fill Pits and Clean Up Location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Operator</u>	DATE <u>7/8/77</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR, DISTRICT R</u>	DATE <u>JUL 18 1977</u>
CONDITIONS OF APPROVAL, IF ANY:		