

1/2 3/4" at 27' w/2 yds

[illegible]

SUSPENDED OPERATIONS

3878' GL 1200' RT

2-7-78 Drlg 55'
 3-14-78 Drlg 340'
 3-20-78 Drlg 365'
 3-27-78 Drlg 425'
 4-4-78 Drlg 475'
 4-10-78 Drlg 490' 1m
 4-17-78 Drlg 525' 1m
 4-25-78 Drlg 610'
 5-2-78 TD 610'; SD
 5-9-78 Drlg 664' 1m
 5-15-78 Drlg 720' 1m
 5-23-78 Drlg 723' 1m
 5-30-78 Drlg 770' 1m
 6-6-78 Drlg 833' 1m
 6-12-78 Drlg 886' 1m
 6-19-78 Drlg 898' 1m
 6-26-78 Drlg 977'

11-1-11 NM

EDDY
YATES, HARVEY E. CO.

Wildcat
1 China Canyon ARCO Fed. Page #2
Sec 28, T23S, R24E

7-10-78	Drlg 1075'
7-18-78	Drlg 1135' sdy & lm
7-24-78	Drlg 1177'
7-31-78	Drlg 1220'
8-7-78	Drlg 1265'
8-14-78	TD 1320'; Circ
8-21-78	TD 1320'; SI/WO
8-24-78	TD 1320'; Converting to Water Well
10-30-78	TD 1320'; Suspended Operations
11-4-78	COMPLETION ISSUED

11-1-11 NM
IC 30-015-70044-78