

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease State ☒ Fee ☐
3. State Oil & Gas Lease No. L-711
7. Unit Agreement Name
8. Farm or Lease Name Amoco 22 State
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated Strawn
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG WELLS IN ANY OTHER RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, NM 88201	4. Location of Well UNIT LETTER <u>E</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>22</u> TOWNSHIP <u>23S</u> RANGE <u>27E</u> NMPM.

JUN 22 1987
O. C. D.
ARTESIA OFFICE

15. Elevation (Show whether DF, RT, CR, etc.) 3148.6 GL
--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

Plug back & test Strawn

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

- 5-12-87 Set 5½" CIBP @ 10,905', Dump 35' cmt on top. New PBTD @ 10,870'.
- 5-14-87 Perf 2 JSPF through tbg @ 9972-78' & 9998-10,005', 28 holes. Broke down perfs w/200 gals 15% NEFE acid. Flow well to pit to clean up.
- 5-20-87 Perf 2 JSPF through tbg @ 9268-72' and 9118-24, 22 holes. Acidize w/7000 gals 20% NEFE; acidized w/10,000 15% NEFE.
- 5-28-87 Acidize 9268-72' w/1500 gals 20% NEFE & 5000 gals 20% HCL
- 6-2-87 Roll hole w/10# brine & retrieve RBP & pull pkr & RBP to 9850' and set pkr. Open well to pit and test for 2 hours. Flow well on 32/64" choke after clean up for 2 hours @ 650# FTP.

Post FD-2
7-17-87
ALA AtoK9

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Ray J. Clements TITLE Production Manager/Engineer DATE June 17, 1987

Original Signed By
Les A. Clements

APPROVED BY _____ TITLE _____ DATE JUL 14 1987