

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
SEP 24 1991

O. C. D.

WELL API NO. 30-015-22545
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-490
7. Lease Name or Unit Agreement Name Mobil 21 State
8. Well No. #2
9. Pool name or Wildcat S. Carlsbad Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3162.4 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202
4. Well Location Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line Section 21 Township 23S Range 27E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Perf & acidize; test <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP @ 11,670' w/35' cmt
- 2) Set retainer @ 5800' to block squeeze
- 3) Perf & test Bone Spring interval
- 4) Above procedure to allow going back down hole at later date

Approval given by Darrell Moore on 9/23/91

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tim Gum TITLE Engineer DATE 9/24/91

TYPE OR PRINT NAME Tim Gum TELEPHONE NO. 623-6601

(This space for State Use)

APPROVED BY Mike Walker TITLE SUPERVISOR, DISTRICT II DATE OCT 4 1991

CONDITIONS OF APPROVAL, IF ANY: