


EDDY Herradura Bend
EASTLAND OIL CO., THE
1 State "32"
Sec 32, T22S, R28E
2160' FSL, 320' FWL of Sec
7 mi SE/Carlsbad

15-22679

8 NM

10-78

6 5/8" at 379' w/210 sh
4 1/2" at 1512' w/500 sh



IP (Delaware) 1-1-78 + 13 BW + 71 BW
Pot based on 24 hr test: GOR TSEM; July 41.8

Corros

1060 11

CT

9-11-78
(Delaware)
9-16-78 TD 135'; 3ng Csg
9-26-78 TD 325' sh; SD/Weather
10-3-78 Drilg 950' anhy
10-11-78 TD 1030'; SD/Repair
10-26-78 TD 1030'; Prep Drill
10-31-78 Drilg 1220'
11-7-78 Drilg 2090' salt
11-14-78 TD 2512'; WOC
11-28-78 TD 2512'; WO/Pmp
Perf (Delaware) 2469-79' w/1 SF
Acid (2469-79') 500 gals (7-1/2)
Frac (2469-79') 3000 gals + 3000
12-5-78 TD 2512', Ppg Ld
Fpd 78 BW + 13 BLW in 24 hrs (2469-79')
12-12-78 TD 2512'; TOP
Fpd 7 EO + 85 BW in 24 hrs (2469-79')
1-1-79

EDDY
EASTLAND OIL CO., 7171

Herradura Bend
1 State 132"
Sec 22, 22S, 22W

10-2

12-18-78

27 15:11' 10SP

Top 2 1/2' 21 1/2' 24 hrs (2400)

1-1-79

Top 2 1/2' 21 1/2' 24 hrs

Top 2 1/2' 21 1/2' 24 hrs

Top 2 1/2' 21 1/2' 24 hrs

Top 2 1/2' 21 1/2' 24 hrs

Top 2 1/2' 21 1/2' 24 hrs

1-8-79

Top 2 1/2' 21 1/2' 24 hrs

1-8-79

1-8-79