

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
ALBUQUERQUE, NM 88210

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

215F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Exxon Corporation Attn: Janet L. Schaumburg		8. FARM OR LEASE NAME Gourley Federal Com.	
3. ADDRESS OF OPERATOR P. O. Box 1600, Midland, TX 79702		10. FIELD AND POOL, OR WILDCAT Sec. 28, T22S, R28E	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL and 1980' FEL of Sect.		11. SEC., T., R., OR BLE. AND SURVEY OR AREA Sec. 28, T22S, R28E	
14. PERMIT NO.	15. ELEVATIONS (Show whether SP, RT, OR, etc.) 3080 KB	12. COUNTY OR PARISH Eddy	13. STATE NM

RECEIVED BY  
AUG 25 1986  
O. C. D.  
ARTESIA, NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANE	(Other) Temporary Abandon	X
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Only one zone in this dual completion is TA'd. The Atoka is currently producing and the Morrow does not have a sales contract. The Morrow tubing string also has junk in the hole which prevents us from producing it with out first killing the Atoka. We therefore plan on depleting the Atoka before attempting to bring the Morrow on line.

18. I hereby certify that the foregoing is true and correct

SIGNED Janet L. Schaumburg TITLE Permits Supervisor DATE 8-18-86  
Janet L. Schaumburg

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

\*See Instructions on Reverse Side

AUG 21 1986