N.M.O.C.D. COPY Form 9-331 (May 1963) Form approved. Budget Bureau No. 42-R1424. SUBMIT IN TI ICATE. DEPARTMENT OF THE INTERIOR (Other in verse side) 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY NM-15295 6. IF INDIAN, ALLOTTER OR TRIBE NAME. SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a directive of Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME OTHER Lost Hole \$ 1980 NAME OF OPERATOR S. FARM OR LEASE NAME C & K Petrcleum, Inc. "CK" Federal AUDRESS OF OPERATOR 9. WELL NO. P.O. Drawer 3546, Midland, Texas 79702 to extres of well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) V. surface 10. FIELD AND POOL, OR WILDCAT Wildcat 1650' FSL & 1781' FEL, Sec. 8, T-24-S, R-26-E, Eddy co., NM 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 8, T-24-S, R-26-E 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. CERMIT NO. 12. COUNTY OR PARISH! 13. STATE 3481.9 Eddy Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PULL OR ALTER CASING REPAIRING WELL EST WATER SHUT-OFF MULTIPLE COMPLETE ALTERING CASING ABANDON* P/A SHOOL OR ACIDIZE SHOOTING OR ACIDIZING ABANDONMENT* (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Others 17 DESCRIPE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) • Following is our intended Plugging procedure: Plug #1 - 30 sx. cement plug inside 8-5/8" csg. 1653-1553'. Plug #2 - 150 sx. cement plug 1100' - 600' 8-5/8" casing was shot off @ 700'.) (Note: Plug #3 - 25 sx. cement plug inside 14" conductor pipe 30' to surface.