

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 14 1994

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-23300
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Kaiser-Francis Oil Company		6. State Oil & Gas Lease No. -
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468		7. Lease Name or Unit Agreement Name Vasquez Com
4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>1925</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>24S</u> Range <u>28E</u> NMPM <u>Eddy</u> County		8. Well No. 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 301 GR		9. Pool name or Wildcat Malage (Delaware)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following is our proposal to plug & abandon the above well:

- Set cmt retainer @ 6075' & pump 35 sxs cmt. Sting out of retainer & dump 2 sxs cmt on top. Plug 2445' - 2612
- Cut off 9 5/8" casing & pull (est. 1200').
- Set 75 sx cmt plug 50' in and out of casing stub.
- Set 75 sx cmt plug from 480' - 380'.
- Set 25 sx cmt plug from 30' to surface.
- Cut off casing & install dryhole marker.

Estimated starting date: 2/15/94

Note: (6/93) CIBP set @ 11595' w/50' cmt on top. Set 50 sx cmt plug from 11150' - 11050'.
Set 50 sx cmt plug from 9450' - 9350'.
Delaware perfs @ 6096' - 6181' o.a.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. Jan Valkenburg TITLE Technical Coordinator DATE 1/12/94
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature]

TITLE [Signature]

DATE 2/9/94

CONDITIONS OF APPROVAL, IF ANY: