NU. OF COMILS PCC DISTRIBUTI SANTA FE		NEW MEXICO OIL CONSERVATION COMMISSIC.			MISSIC	Form C + 103 Supersedes Old C + 102 and C + 103 Effectivo 1 + 1 + 65			
FILC	Z			RECEIVED		Sa. Indicate Type			
U.S.G.S.				DEC 24 1980	า	Stote 5. State Off & Ga	Fee X		
OPERATOR	/ _			UE6 24 1300	J	5. State Off & Ga	a Leose Not		
LDO NOT US	SUND: E THIS FORM FOR MAN	AY NOTICES AN	D REPORTS ON	WELLS	T RESERVOIR.	7. Unit Agreemen			
1. 011 X	GAS	OTHER-				7, Olite Aspectation			
VILL LAJ		/				8. Farm of Lease			
Delta Drilling Company /							South Culebra Bluff 9. Well No.		
1. Address of Opera		1 1 1 2 70	700			6			
P. O. Box 3467 Midland, Texas 79702 4. Lecution of Well Whit Letter E 1980 FEET FROM THE North Line AND 660 FEET FROM							10. Field end Fool, or Wildest South Culebra Bluff Unit (Bone Spring)		
UNIT LETTER	<u> </u>	1980 FEET FRC	MINE North	LINE AND	DU FEET FROM	(Bone S			
THE West	LINE, SECTI	он24	TOWNSHIP	RANGE	3-Е кмры.				
TITITITI T	<u>UIIIIII</u>	$\langle \rangle \rangle \langle \rangle \langle \rangle \langle \rangle$		DF, RT, GR, etc.	) .	12. County Eddy			
MIIII	<u> </u>		3004 Gr		D wast of Oth		-77777777777777777777777777777777777777		
16.		Αρριορείατε Βο: ΝΤΕΝΤΙΟΝ ΤΟ:	x To Indicate .	Nature of Noti-	CC, Report or Ot SUBSEQUENT	r REPORT OF:			
PERFORM RENEDIAL		PLV	G AND ABANDON	REMEDIAL WORK	ING OPNS.		ING CASING		
TEMPORARILY ABANG	<u> </u>	¢ HA	NGE PLANS	CASING TEST AND	r		X		
OTHER									
17. Describe Propo	used or Completed O	perations (Clearly st	ate all pertinent de	tails, and give peri	tinent dates, including	estimated date of	starting any proposed		
work) SEE RUI	LE 1103. RU an	d run 4-1/2"	11.0% 1 00		_				
			Le	ength 16.13	Depth 6801.82				
	Hanger	211 11 6# N-80	6817.95						
	63 Jts 4-1/ Landing Col	2" 11.6# N-80	/ 2.	536.36 0.88	9454.31				
	Float Colla			1.67	9455.19				
		11.6# N-80		41.61	9456.86				
	Float Shoe	11.0% 1 00		1.53	9498.47				
10/24/80	Cemented with 450 sacks class H 50/50 poz mix with 5# KCL, 0.3 of 1% Halad 22, 0.5 of 1% CFR-2, 2% gel mixed at 14.3#/gal with a yield of 1.27 cubic feet per sack. Pumped at 4 BPM at 1500# to displace. PU second plug at 1/2 BBLS over displacement, bump plug at 2000# w/80.5 BBLS displacement (0.5 BBLS over calculated displacement). Released pressure and float held. Pulled out of liner. Had good circulation throughout job. Pulled out of hole with 2-7/8" tubing WOC.								
	(continued	on back)							
		· · · · · · · · · · · · · · · · · · ·	molete to the best	of my knowledge	and belief.				
18, 1 hereby certify	that the informatio	n above is true and c	omplete to the peri	, st my nuesteeps .					
SIGNED	Achile.	cont in-	TITLE DI	vision Produ	iction Manager	DATE	8/80		
	mhall	illion.		IL AND GAS 1887	733.08	DATE DE	C 2 9 1960		
CONDITIONS OF	APPROVAL, IF AN	<u> </u>	<del>~~</del>						

.

CONDITIONS OF APPROVAL, IF ANYI

10/27/80 RIH w/6.75" bit and work string to TOC @ 6180'. Reverse circulate @ rate of 2 BPM @ 200 psi. Running 5 points on bit @ 40 RPM. Drilled hard cement from 6595' to 6807'. Circulate hole clean. Tested liner top to 3000 psi for 30 min. Tested o.k. Pulled out of hole with tubing and bit. RIH w/88 jts 2-3/8" 4.7# J-55 tbg w/cement mill and casing scraper. Worked mill into liner. Drilled 5' cement. Tbg began to torque up. POOH w/tbg mill and scraper. RIH w/tbg and mill only and drilled to 6819'. Fell out of cement @ this point. Circulate hole clean. RIH to 9370'. Drilled cmt down to 9450'. Circulate hole clean. Tested liner to 3000 psi for 30 min. Held o.k.