

-This P-A was never reported on IDA; we don't have a C105 in file showing it to be completed as such.

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	✓
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

Please report both forms immediately  
Form C-102 and C-103  
Supersedes Old  
Effective 1-1-65

RECEIVED  
MAR 05 1981

SEP 12 1980

O. C. D.

ARTESIA, OFFICE

9. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

LG-0687

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> DRY HOLE	7. Unit Agreement Name
2. Name of Operator Orla Petco, Inc. ✓	8. Farm or Lease Name Collins-State
3. Address of Operator P.O. Box 1383, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>24S</u> RANGE <u>27E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat <u>Del</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3204.0' Ground	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/31/80 - Spudded well.

9/08/80 - Plugged and Abandoned well with the following plugs:

Plug #1 - 35 sx Class C from 2100'-2200'.

#2 - 35 sx " " " 1820'-1920'.

#3 - 35 sx " " " 1050'-1150'.

#4 - 60 sx " " " 300'-435'

15 sx on surface. Tagged 4th plug after set up. Then put in 15 sx on surface. Mud laden brine water between all plugs.

NO CLOSURE

2-11-80

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Vice-President

DATE September 11, 1980

APPROVED BY

TITLE OIL AND GAS INSPECTOR

DATE MAR 03 1981

CONDITIONS OF APPROVAL, IF ANY: