· · · ·									
NO. OF COPIES RECEIVED				Form C-103					
DISTRIBUTION			Supersedes Old C-102 and C-103						
SANTA FE	1		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65					
FILE	1	1							
U.S.G.S.				Sa. Indicate Type of Lease					
LAND OFFICE				State Fee X					
OPERATOR	1			5. State Oil & Gas Lease No.					
L									
(DO NOT USE THIS FO									
1.			RECEIVED	7. Unit Agreement Name					
OIL GAS	ιL	3	OTHER-						
2. Name of Operator	8. Farm or Lease Name								
Cities Servic	Brantley A Com								
3. Address of Operator		· •		9. Well No.					
P. O. Box 191	9. M	1idl	and, Texas 79702 O. C. O.	1					
4. Location of Well			ARTESIA, OFFICE	10. Field and Pool, or Wildcat					
J			1980 FEET FROM THE South LINE AND 1980 FEET FRO	Und. N. Loving Mor.					
UNIT LETTER		,							
East			DN TOWNSHIP 23S RANGE 28E NMPN						
THE	LINE.	250110	NA RANGE NMPM	. ΥΠΗΠΗΠΗΠΗΠΗΛ					
	12. County								
$\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi(\chi($	Eddy								
16.	Ċb.	مدلا	Appropriate Box To Indicate Nature of Notice Report of O	the Data					
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:									
NOT				TREFORT OF.					
PERFORM REMEDIAL WORK	٦		PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING					
TEMPORARILY ABANDON	7		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT					
PULL OR ALTER MASING	4		CHANGE PLANS CASING TEST AND CEMENT JOB	PEDG AND ABANDONMENT					
				· · · · · · · · · · · · · · · · · · ·					
OTHER									
Unch									
-11 and -100 -100			perations (Clearly state all pertinent details, and give pertinent clates, includin						
work) SEE ROLE 1103. T.D. 10,946'LM & Shale. Prep to drill ahead. Drilled a 8 ¹ / ₂ " hole to a T.D. of 10,940' in Lime and									
Shale. Ran and s	Shale. Ran and set 30 Jts (1138.74') 7" OD 29# S-95, 77 Jts. (3408.62') 7" DD 26# S-95 and 163								
$\frac{1000}{100}$ Share. Rain and See 50 000 (1150.77) / 02 25% 2 50, 11 100 (0.5520'. Cemented 1st stg w/165									

Jts. (6374.44') 7" OD 23# S-95 casing @ 10,940' with a DV tool @ 5520'. Cemented 1st stg w/165 sx Trinity Lite at 12.5#/gal w/3/4% CRR-2 & 1/4# Flocele /sx, followed by 635 sx Cl H at 16#/gal w/3/4% CFR-2 & 1/4# Flocele/sx & 5# KCL/sx. PD on 1st stg at 1000 MST 1-8-81 w/2200#-held OK. Had full circ on 1st stg. Dropped bomb and opened DV tool at 5520'. Circ 4 hrs between stgs & circ 100 sx from stg #1 to pit. Cmtd 2nd stg w/700 sx Trinity Lite at 12.5#/gal w/1/2% CFR-2 & 1/4# Flocele/sx, followed by 100 sx Cl H at 12.5#/gal w/1/2% CFR-2. PD on 2nd stg at 1700 MST 1-8-81 w/1500#. Held OK. Circ 200 sx to pit from 2nd stg. Because of overpressured zones in the Atoka, prior to running 7" casing, it was decided as a matter of safety and good operating practice to back up the 7" casing by circulating cement to the surface through a DV tool set @ 5520'. WOC 31 hrs. Tagged DV tool at 5520'. Drld DV & tstd csg & DV to 1000# - OK. Drld FC & 1/2 of cmt in shoe jt. Tstd csg 1000# for 30 min - OK. Drld rest of shoe jt & 6' of new form to 10,946'. RU Halco. Tstd shoe to 14.4#/gal equiv MW by press 10.5#/gal fluid to 220# at surf - OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	Sfluiden	Region Oper. Mgr.	DATE	Jan. 14, 1981
APPROVED BY _	While Williams	TITLE	OATE	JAN 18 100
CONDITIONS	OF APPROVAL, IF ANY:			