Submit 3 Copies to Appropriate District Office

DOUGH WE'LL AN END Ener Minerals and Natural Resources Department

Form	C	.1Q	,
Revie	×	1-1	4

rm C-103 related 1-1-89	d

DISTRIC	LI			
P.O. Box	1980,	Hobbs,	NM	88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe, New Mexico 8750##QENED

WELL API NO.	
30-015-23521	
5. Indicate Type of Lease	<u>~</u>
STATE	FEE 🔼

		NOV 9 E 1001	STATEL	FEE ∟
Aziec, NM 87410		NUV 2 3 1331	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND P	REPORTS ON W	ELLSARTESIA OFFICE		

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN	OR DILLO CACY TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	
WELL [X] WELL OTHER	Kimbley
2. Name of Operator	8. Well No.
Bird Creek Resources. Inc.	1
3. Address of Operator	9. Pool name or Wildox
810 S. Cincinnati, Suite 110 Tulsa, OK	74119 S. Culebra Bluff Bone Spring
1	
Unit LetterG : _1830 Feet Prom TheNorth	Line and 2060 Feet From The East Line
Section 21 Township 23-S Rate 10. Elevation (Show whether it	age 28-E NMPM Eddy County
10. Elevation (Show whether)	OF, RKB, RT, GR, etc.)
11. Check Appropriate Box to Indicate N	Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOS
OTHER:	OTHER: Permanently abandon Delaware X

12. Describe Proposed or Completed Operations (Clearly state all persisent datails, and give persisent dates, including extinated date of marring any proposed work) SEE RULE 1103.

Well has been producing from Bone Spring @ 6212-31' under pkr. with Delaware open (behind tbg.) @ 6038-66'. This is the report of cmt. squeezing the Delaware and putting the Bone Spring on pump.

- RUPU. Released pkr. @ 6150' and TOH. TIH w/ CIBP on tbg., set @ 6151'. TOH 11-12-91
- TIH w/ RTTS pkr., set @ 5829'. By Western, squeezed Delaware perfs @ 6038-66' 11-13-91 w/ 100 sxs. premium cmt., 5% salt to 1250#. WOC.
- TOH w/ pkr. TIH w/ bit and DO cmt. @ 5924-6066'. Tested squeezed perfs to 1000#, 11-14-91 30 min., held OK. Drilled and pushed CIBP to 6434'.
- TOH w/ bit. TIH w/ production equipment. NDBOP, NUWH. RDPU. Put well on test. 11-15-91 Lost 300 BW into Bone Spring.

I bereby certify that the infor	matics above is true and completery the best of any bace D. Books	redge and belief.	DATE 11-22-91
TYPE OR PRINT NAME BY	ad D. Burks	918-582-3855	TELEPHONE NO.
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS SUPERVISOR, DISTRICT IT		0FC :: e +001
APPROVED BY	and the state of t	mu	DEC = 3 1991