


Operator Newbourne Oil Co.
 Well State IX Gas Co. #1
 Unit H Section 6 Township 24 Range 25
 API # 30-015-23523

TOPS

Neef	0-?
Delaware	~2785
Base Spring	4780
Wolfcamp	8421
Penn	9186
Strawn	9440
Atoka	9748
Marathon Limestone	10250
Marathon Clastics	10480
Barnett	10898

- * Contact OCD 24 hrs. prior to any work done.
- * Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug.
- * Install dry hole marker as per Rule 202.B.2
- * Plugs are to be set from point indicated up.
- * Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- * Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- * Surface plug will be from 0' - 60'
- * Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists.
- * Plugs to be tagged will be indicated.



10.