Do not use this form for Use "AP	UNITED STA DEPARTMENT OF TH BUREAU OF LAND M PRY NOTICES AND RE proposals to drill or to de PLICATION FOR PERMIT	E INTERIOR ANAGEMENT PORTS ON WELLS	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
Do not use this form for Use "AP 1. Type of Weil	BUREAU OF LAND MARKED BUREAU OF LAND MARKED BUREAU OF LAND MARKED BUREAU OF LAND RE	ANAGEMENT PORTS ON WELLS	Expires: March 31, 1993
Do not use this form for Use "AP 1. Type of Weil	PRY NOTICES AND RE	PORTS ON WELLS	
Do not use this form for Use "AP 1. Type of Weil	proposals to drill or to de		5. Lease Designation and Serial No
1. Type of Weil		eppen or reentry to a different re ''' for such proposals	eservoir.
	SUBMIT IN TRIP		7. If Unit or CA, Agreement Designation
V Well Gas Othe			
2. Name of Operator		or 05'	8. Well Name and No.
Pogo Producing Com	pany	(915)682-6822	94 <u>Nel Com #1</u> 9. API Well No.
3. Address and Telephone No.		0. C. I	D.
P.O. Box 10340 Midland, Texas 79702-7340TESIA, OFFICE 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			OFFICE 10. Field and Pool, or Exploratory Area
			N. Loving Morrow
660' FEL & 1980' F	SL, Sec. 9, T23S, 1	₹28E	11. County or Parish, State
			Eddy County, NM
2 CHECK APPRO	PRIATE BOX(s) TO IN	DICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
TYPE OF SUBMISS			ACTION
Notice of Intent			<u> </u>
		Abandonment	Change of Plans New Construction
Subsequent Report		Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
Final Abandonment I	Notice	Altering Casing	Conversion to Injection
		Other	(Note: Report results of multiple completion on Well
3. Describe Proposed or Completed Oper give subsurface locations and me	ations (Clearly state all pertinent detail	ls, and give pertinent dates, including estimated di I markers and zones pertinent to this work.)*	Completion or Recompletion Report and Log form 1 fate of starting any proposed work. If well is directionally drilled.
In response to your	r letter (copy atta	iched) the Nel Com #1 is rom the Morrow Formation	still an since July 1990.
			0
			Ser Ser
		,	SEP L
		,	Sep L
		J. Lana - 3 1991	
		,	
		,	
		,	
		,	
		,	
		,	
	by and correct	J. La u - 3 1994	
4. 1 hereby certificate the foregoing is	the and correct	J. Lin - 3 1990	
4. I hereby certify that the foregoing is Signed	the and correct	J. Liu - 3 1994 <u>• Division Operations E</u>	



United States Department of the Interior

RECEIVED BUREAU OF LAND MANAGEMENT Carlsbad Resource Area Headquarters AUG - 0 1994 P.O. Box 1778 Carlsbad, New Mexico 88221-1778

IN REPLY REFER TO-

MIDLAND, SIGL

AUG 0 8 1994

CERTIFIED---RETURN RECEIPT REQUESTED Z 730 341 209

Pogo Producing Company P. O. Box 10340 Midland, TX 79702-7340

SCR89/NM-15433; NEL Com No. 1 RE: NESE, Sec. 9, T23S, R28E Eddy County, New Mexico

Gentlemen:

Our records show the above referenced well is operated by you and is reported as Shut-In (SI) or Temporarily Abandoned (TA). The Bureau of Land Management (BLM) and Minerals Management Service (MMS) definition of a shut-in well is a completion that is physically and mechanically capable of production in paying quantities or capable of service use. The definition of a temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have value as a service completion. According to our records the well referenced above has been shut-in for 6 months or longer or has been temporarily abandoned without authorization. 43 CFR 3162.3-4(c)requires that wells incapable of production in paying quantities be promptly plugged and abandoned and requires approval for any well temporarily abandoned for more than 30 days.

Accordingly, you are to take one of the following actions:

- 1. Return the well to production or beneficial use.
- 2. Plug and abandon the well.
- 3. Request approval for temporary abandonment and include a schedule for casing integrity testing.

If you decide to return the well to production or beneficial use, submit a Sundry Notice of intent within 30 business days of receipt of this letter. Include the date you anticipate the well being placed back in service. Use Form 3160-5 and submit the original and 5 copies for each well. 43 CFR 3162.4-1(c) also requires you to notify the Authorized Officer, not later than the fifth business day after production is resumed for any well which has been off production for more than 90 days, the date on which such production was resumed. Notification may be by letter or Sundry Notice, or orally followed by letter or Sundry Notice.

If you decide to plug and abandon the well, submit a separate Sundry Notice (Form 3160-5, original and 5 copies) within 30 business days of receipt of this letter and describe the proposed plugging program.