STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		\mathbb{L}
SANTA FE	\perp	1_
FILE	1	1/
U.1.G.1.	1_	
LAND OFFICE		
OPERATOR		ł

IL CONSERVATION DIVISIO.

Form C-103

DISTRI	BUTION	1		. 2088)		Revised 10-1-1	
SANTA FE		SANTA	A FE, NEW	MEXICO 87501	-		·	
FILE		1		A Section of the sect		Sa. Indicate Type		
U.S.G.S.		1			11	State X	Fee	
LAND OFF	ICE	1			i i	5, State Oil & Go	as Lease No.	
OPERATOR		}			- 1	L-5157		
<u></u>						mm	mmm	
	SUNDR	Y NOTICES AND RE	PORTS ON	WELLS	, i	///////////////////////////////////////	///////////////////////////////////////	
SUNDRY NOTICES AND REPORTS ON WELLS [DO NOT USE THIS FORM FOR PROPOSALS TO PRILL ON TO DEFEN OR PLUG BACK TO A DIFFERENT RESERVOIR.						VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII		
	USE "APPEILATI	TOR FOR PERMIT = (1 CM.)				7. Unit Agreemer	nt Nanie	
1.	6A8 [77]							
writ L	WELL X	OTHER-				8. Farm or Lease	e Liame	
2. Name of Contract					l			
Pogo Producing Company						MAW State		
3. Address of Carrator						9. Well No.		
		Morros 7070	n			1		
P.O. Box 10340 Midland, Texas 79702						10. Field and Pool, or Wildcat		
4. Location of well								
1	ਸ 19	180	North	LINE AND	FEET FROM	WIIGCAL	MOTTOM	
UNIT LETTER.	,,,	FEET FROM THE						
		3.4	24 C	27. 5	1			
Wes	t LINE, SECTIO	on <u>14</u> town	SHIP	RANGE27-E	нмрм. 🖟	///////////////////////////////////////		
						7777777	444444	
TITITITI	THITTIP.	15. Elevation	(Show whether	DF, RT, GR, etc.)		12. County		
			3165 G	R	ļ	Eddy	7777777	
011111111	77777777	711117			0.1	- D		
16.	Check	Appropriate Box To	Indicate N	ature of Notice, Repo	rt or Utne	er Data		
		NTENTION TO:		suas	EQUENT	REPORT OF	:	
	NOTICE OF III	., _,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
	_				\Box	ALTE	AING CASING	
PERFORM REMET	A_ WORK	PLUG AND	ABANDON	REMEDIAL WORK	\exists		7	
TEMPORABILY 414	r-1			COMMENCE DRILLING OPNS.		PLUG	AND ABANDONMENT	
		CHANGE !	LANS	CASING TEST AND CEMENT JOI	. [X]		-	
PULL OR ALTER CA	131MC			OTHER				
OTHER								
				il- and sine pertinent dates	including	stimated date of	starting any propose	
17. Describe Fra	cased or Completed Or	perations (Clearly state a	ll pertinent det	ails, and give pertinent dates,	, the tading c	,	, , , , ,	
work) SEE =								
1-29-81:	30' Drilled	starting hole,	ran 45' (of 20" conductor p	ipe.			
1-30-81.	30' Cemente	ed conductor pipe	e w/3 vds	ready-mix. Drille	ed mouse	e & rat hol	.e.	
	1051 02121	45! in shale M	J 8 6 771	32. Continued ho	le w/dr	la ria @ 1:	:30 am MST	
2-15-81:		.45 III SILATE, IM	V 0.0, VI.	J. J. Concinaca no.	,	-55 9		
	2/15/81.			(0)	F	3	Chao A	
2-16-81:	520' MW 8.8	#. Ran 12 jts	(519.54')	13 3/8" 54.50# K-	55 STC 1	kge 3 CSg.	SIDE 6	
	519', FC @ 4	78' centralize	rs on $1,3$,5 & 7th jts. HOW	30 cemer	ted w/525	sxs CI C	
	+ 2% Ca Cl ₂ .	,	•	_				
0 77 01	5001 Binink		OO om MCT	2/16/81. Circulat	Fed 65 9	3x5. WY 21	hrs. NU	
2-17-81:	520. Finish	cenercing e or	oo an ra	2/10/01. CITCUIA	cca os .	MB / 1100 L		
	BOE, test bl	inds w/1000#, O	K, RIH ar.	lg assy.			C	
2-18-81:	2½ hrs co ce	ment, test casi	ng w/1000:	for 30 minutes, (ok. Dri	TIT suce &	iomation	
	to 953'. MW							
	00 333 • 12.	312 // 5						
18. I hereby cer.	y that the information	shove is true and comple	ete to the best	of my knowledge and belief.				
•	_	•						
	11.1		D.	ivision Operations	Manager	cMarch	1 11, 1981	
\$16HED 4	Blille	amy	TITLED.	TTELOT. OPETACIONS				
	1							
,	11 1	1 11				RA /	AR 1 7 1981	
4	4/11 · 1 .	/ //.		ALL AND GAS IMPOSETOR		[Y 1/	5.1 (130)	