N '. OF COPIES RECEIVED					Form C -103
DISTRIBUTION			8£	CEIVED	Supersedes Old C-102 and C-103
SANTA FE	i	NEW MEXICO OIL CO	• 4 33		Effective 1-1-65
FILE	11				
U.S.G.S.			APR.	1 3 1981	5a. Indicate Type of Lease
LAND OFFICE		·			State Fee X
OPERATOR	7		O.	C. D.	5. State Cil & Gas Lease No.
	<del> </del>			IA OFFICE	
	SLINDE	Y NOTICES AND REPORTS (			
(DO NOT USE THIS FO	STAPPLICAT	Y NOTICES AND REPORTS OF PLUTON FOR PERMIT - " FORM C-1011 FOR S	G BACK TO A DIFFERENT RES	SERVOIR.	
1.					7, Unit Agreement Name
OIL GAS WELL WELL	. 🔯	OTHER-			
2. Name of Operator	·				8. Farm or Lease Name
Coquina Oi	1 Corp	oration 🦯		ł	Nymeyer
3. Address of Operator	<u>'</u> .				9. Well No.
P. O. Draw	er 296	O, Midland, Texas 7970	12		1
4. Location of Well	<u> </u>	3, IIIdialia, Texas 7570	, <u>C</u>		10. Field and Pool, or Wildcat
F		1980 FEET FROM THE West	2210	,	Undesignated North
TOUNIT LETTER	FEET FROM	LOXIDO MOLLOM			
Nonth		15 /	225		
THE MUTUIL	INE, SECTI	on <u>15</u> township <u>2</u>	.33 RANGE2	XE NMPM.	
mmmm	mn	15. Elevation (Show wheth	er DF RT GR etc.)		12. County
		3001' GR	or ary king only every		V///////
11111111111111111111111111111111111111	77777	77777		<del></del>	Eddy ////////
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data					
NOTIC	CEOFI	ITENTION TO:		SUBSEQUENT	REPORT OF:
<del></del>	,	F		<del></del>	
PERFORM REMEDIAL WORK	]	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	]	_	COMMENCE DRILLING	OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	]	CHANGE PLANS	CASING TEST AND CEM	-	
			OTHER Spud D	Date X	
OTHER			_		
17 Describe Figures of on Co	malated Co	acations (Classic state all postinent)	dataila and sina parti-and	• dasa (n.1);	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
Cruddad 0 0 00					
Spudded @ 8:00 a.m. 4/5/81. Drld to 400'.					
Don 0 ita 201 04 1 40 CTO 0					
Ran 8 jts 20" 94# H-40 STC Csg 320'					
Set @ 301 '					
0.111.4450					
Cmt'd w/450 sxs Howco light w/1/4# flocele, and 2% CaCl. Tailed in w/200 sx Cl C					
w/2% CaCl. PD @ 7:00 p.m. 4/6/81. Circ 120 sxs to pit. WOC 18 hrs. Cut 30"					
conductor and 20" casing and weld on flange. NU Hydril, test to 500 psi for 30 min.					
Held o.k. Tag cmt @ 254'. Drill cmt, FC, and shoe. Now drlg.					
18, I hereby certify that the i	nformation	above is true and complete to the bea	st of my knowledge and be	elief.	
ROD M	D. ~	,	Dailling Massa	0.00	April 9, 1981
SIGNED Duly 111.	-rul	Y TITLE	Drilling Manag	er	DATE
	Λ				
/ For R	ecolar	alace of the	SUPERVISOR, DIST	TRICT II	APR 1 4 1981

CONDITIONS OF APPROVAL, IF ANY: