STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	1	
DISTRIBUTION		
SANTA FE		
FILE		1
U,\$.G,\$.		
LAND OFFICE		
OPERATOR	7	Γ

OIL CONSERVATION DIVISION

DISTRIBUTION		P. O. BOX 2088		Form C-103 Revised 10-1-78	
CIUR	+-	SANTA FE, NEW	MEXICO 87501		
U,\$.G,\$.				5a, Indicate Type of Lease	
LAND OFFICE	- 			State Fee XX	
OPERATOR	:	•		5, State Oil & Gan Leuse No.	
<u> </u>					
SI	INDRY NOTICES	AND REPORTS ON	WFI I S	MILLIANIA STATE	
(UO HOT USE THIS FORM F	TOR PROPOSALS TO DRILL	L OR TO DELPEN OR PLUG I	WELLS CHARACTO A CHARACTER SECTION OF		
1.		1,000,000	Ch PAGFOSACS.	7: Unit Agreement Name	
OIL XX WELL	7		#110 O		
2, Name of Operator	OTHER-		AUG 3 1 1981	8. Farm or Lease Name	
·	,			o, roth of Lease Name	
DINERO OPERATIN	NG COMPANY/		O.C.D	GIOVENGO	
3. Address of Operator			ARTESIA, OFFICE	y. Well No.	
Post Office Dra	awer 10505, M	idland, Texas		1	
4. Location of Well				10. Field and Pool, or Wildcallnd.	
I	1980	South	660	om Culebra Bluff-Bone Spring	
UNIT CETTER	,	T FROM THE	LINE AND FEET FR	TITITIE BIGITALITITIES	
111	25	27.	20 5		
THE WEST LINE,	SECTION25	TOWNSHIP 25-3	S RANGE 28-E NME	··· (
mmmmm	mmm.	5) (61) .1	DE DE CO		
	//////////////////////////////////////	Elevation (Show whether	Dr. KI, OK, etc.)	12. County	
			2991 G?L?	Eddy	
Ch	eck Appropriate	Box To Indicate N	Nature of Notice, Report or C	Other Data	
	OF INTENTION			NT REPORT OF:	
	0	· • ·	30032402	REFORT OF:	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	AEMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		L)	COMMENCE ORILLING OPNS.	PLUG AND ABANDONMENT	
PULE OR ALTER CABING		CHANGE PLANS	CASING TEST AND CEMENT JOB	C	
		e	OTHER	Frac. Well XX	
OTHER			1		
			<u> </u>		
17. Describe Proposed or Comple work) SEE RULE 1103.	ited Operations (Clear	ly state all pertinent det	ails, and give pertinent dates, includi	ng estimated date of starting any proposed	
2, 522					
July 10, 1981:	Swabb well	dry. Remove BO	P & put X-mas tree on.	Rig up Western	
Company in prep. to frac. well. Pump packing out on blender and					
waited on blender to proceed with frac. job. Frac with the folling:					
	warted on b.	tender to proces	od with fide. job. Tra	e with the folling.	
		18000 gallons	CMA 7, NO		
		_			
		28000# Sand 20			
			n 2% KCL water		
		Max. pressure	3400#		
		Average 3200#			
		Min. treating	pressure 2800#.		
	Start flowing	ng well back, go	etting some oil show.		
	Perfs. are	5420-34'.			
		,			
·					
18. I hereby certify that the inform	nation above is true s	nd complete to the best	or my knowledge and belief.		
0	\sim				
*16HED Tanond	a 7 our	an title P	roduction Clerk	DATE August 27, 1981	
\ /	// \				

SUPERVISOR, DISTRICT, 44