HUSKY OIL COMPANY MID-CONTINENT DIVISION DENVER, COLORADO

L

CHRON. REPORT - FRODUCTION DEFT.

PAGE

CALVANI #1 SEC. 29-0225-027E EDDY CO., NEW MEXICO

5

11/05/81 ERESENT_DEEBAIIONS: SITP 1250*, FLARING GAS AT 300* FTP EASI_24_HOURS: SITP 0. FL 6200'. No fillup over night. Swb tbg down to 10,500'. RU Halliburton. Acidized Morrow 11,453-65' & 11,469-74'w/1000 gat Morflo DC acid 7-1/2%. Drop 60 ball seaters. Avg TP 3350*, 4.8 BFM. Acidized w/750 SCF/B nitrogen. Displaced w/2% KCL wtr. ISIP 4300*. Flowed well to pit 2 hrs, died. All wtr. Swb well down to 10,000'. Seems to have had small trace of gas, possibly acid gas. DAILY_COST: \$8,500 CUM._COMEL.1 \$52,650 WELL_COST: \$1,570,302

11/06/81 ERESENT_DEERATIONS: PREF TO PERF NEXT MORROW INTERVAL EAST_24_HOURS: SITF 1250‡, Flowed well to pit, Died in 1-1/2 hrs. Too small blow. Swbd 19 B acid cut wtr from perfs 11,453-65*, 11,469-74*. Swbd down to 10,500*. No fluid entry. Measured gas at 89 MCFD. SWI. DAILY_COSI: \$2,500 CUM._COMEL.: \$55,150 WELL_COSI: \$1,572,802

11/07/81 ERESENT_DEERATIONS: PERFORATING EASI_24_HOURS: SITP 17504. FL 10,150'. 300' fillup over nite. Swbd down down to 10,800'. RW .20, 76 deg. At noon pumped 35 B 2% KCL wtr. RU GO Vann to perforate. Collar located failed on first run. Second run perf'd 11,317-21'. SD. DAILY_COSI: \$3,700 CUM._COMEL.: \$58,850 WELL_COSI: \$1,576,502 11/08/81 ERESENT_DEERATIONS:

SDFS <u>PAST_24_HOUBS</u>: SITE 1700#. Finished perfig 11,353-56, 11,343-47, 11,277-11,286'. TE 200# at end of job. RD GO Vann. Open well to pit. Started unloading wtr immediately. Died in one hour. 4' flare. Swbd. FL 6800'. Swbd to 11,000', 5 runs. SWD. <u>DAILY_COST\$5,500,000 CUM. COMPL.</u>: \$64,300 WELL_COST\$ \$1,582,002