

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

ORIGINAL COPY
SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Form Approved
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.

NM 27919

6. IF INDIAN ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
DINERO OPERATING COMPANY

3. ADDRESS OF OPERATOR
P. O. Drawer 10505, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
660' FNL & 560' FWL
Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RL, or G.L.)
2971' G.L.

7. LEASE AGREEMENT NAME

8. FARM OR LEASE NAME
DEWEY

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
(Bone Springs) Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 24, T-24-S, R-28-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

RECEIVED

SEP 28 1981

G. C. D.

NEW MEXICO

2971' G.L.

Eddy

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☒	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANS	☐	(Other)	☐		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pull tubing & Packer from hole. Lay Packer down & run 2 3/8" tubing in hole open end to 6280'. Install blast joint on top of tubing string in prep. for frac job.

Frac well as follows:

(40,000 gallons of fluid-10,000 gallons CO-2)
Titon XL-3 Done in 2 stages. Ball Sealers (20)
105,500# of Sand. Bone Springs (Upper)**
Max. press. 3500#
Treating press. 2700#
20 barrels per min. average
ISDP 800# 15 min. 700#
1175 barrels load

RECEIVED
AUG 6 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

**Perfs: 6767-68-69-70-71-72-73-74', 6778-80', 6786-88', 6797-6804', 6814-18', 6825-35', 6837-44', 6874-78'.

18. I hereby certify that the foregoing is true and correct

SIGNED Rogers Chapman

TITLE Production Clerk

DATE 8/5/81

(This space for Field Office or RECORD
ROGER A. CHAPMAN

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

SEP 23 1981

U.S. GEOLOGICAL SURVEY See Instructions on Reverse Side
ROSWELL, NEW MEXICO