

MAR - 9 1982

DATE 3/2 19 82O. C. D.
ARTESIA OFFICE

ADVICE ON WELLS TIED INTO GAS GATHERING SYSTEMS

Name of Producer Dinero Operating Company (1814) ✓

Well Name and Number Big Chief Com. #5

Location 1980' FNL, 660' FWL, Sec. 15, T-22-S, R-28-E, Eddy Co., NM

Pool Name Dublin Ranch Atoka

Producing Formation Atoka

Top of Gas Pay 11,470' (Open hole - due to blow out while in Atoka zone)

Oil or Gas Well Gas

Gas Unit Allocation 320 Acres (N 1/2)

Date Tied Into Gathering Systems 2/19/82

Date of First Delivery 2/20/82

Gas Gathering System South Carlsbad G/S (Trk. "C")

Processed through Gasoline Plant (yes or no) No

Station Number 58-554-01

Remarks: This well blew out and was tied in under emergency conditions.

The well will be completed and tested after being connected.

After well stabilizes, the operator wants to recomple to the

Morrow zone; which was the zone originally planned for completion

Site Code: 34893-7-01

By: J. R. Newman, Dispatching