

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

MAY 1985

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator DINERO OPERATING COMPANY	8. Farm or Lease Name COTTON PETROLEUM CO.
3. Address of Operator P. O. DRAWER 10505, MIDLAND, TEXAS 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>430</u> FEET FROM THE <u>North</u> LINE AND <u>550</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>24-S</u> RANGE <u>28-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat-Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3063.8 GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

May 14, 1985: Set C.I.B.P. at 5,866' with 35 feet of cement on top'.  
Freepoint and cut 4½"-10.5# casing at 3,640 feet.  
Pull casing from hole.  
Ran Lyons Packer in hole. Would not go past 2,900 feet. Laid packers down.  
Ran 4½"-10.5# casing in hole to 3,639 feet.  
Cement by Western Company, 260 sacks Class C cement.  
Perforate 4½" at 3,486 feet to 3,494 feet with 2 shots per foot.  
Acidize with 1,500 gallons 15% NE acid, ball sealers.  
Swabb load back with no shows of oil or gas.  
Prep. to P. & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Laverda Norman TITLE Production Supervisor DATE 5/29/85

APPROVED BY \_\_\_\_\_ TITLE Original Signed By  
Les A. Clements DATE JUN 01 1985  
CONDITIONS OF APPROVAL, IF ANY: Supervisor District II