

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO AN EXISTING RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED MAY 31 5:00 ARTESIAN	7. Unit Agreement Name
2. Name of Operator DINERO OPERATING COMPANY		8. Farm or Lease Name COTTON PETROLEUM CO.
3. Address of Operator P. O. DRAWER 10505, MIDLAND, TEXAS 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>430</u> FEET FROM THE <u>North</u> LINE AND <u>550</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>24-S</u> RANGE <u>28-E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat-Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3063.8 GL		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

May 23, 1985: Set C.I.B.P. at 3,866' with 50 sacks cement on top.
Cut 4½" casing at 2,850' and pull out of hole.
100' cement plug. 2,900' up to 2,793' (Tag). 20 sacks.
100' cement plug. 2,463' up to 2,363' (Tag). 75 sacks.
(We had to make 3 attempts to get this plug.)
100' cement plug. 463'-363'. 30 sacks.
60' cement plug. 60' to surface. 15 sacks.
Welded plate over 13 3/8 casing.
Set I.D. marker of 4½" casing.
Job completed 5/28/85.

Post ID-2
6-7-85
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Laverda Norman

TITLE Production Supervisor

DATE 5/29/85

APPROVED BY Larry Brooks

TITLE Geologist

DATE JUN 24 1985

CONDITIONS OF APPROVAL, IF ANY: