

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY  
CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501  
DEC 28 1984  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

3a. Indicate Type of Lease  
State ☒ Fee ☐  
3. State Oil & Gas Lease No.  
L-6658

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Pogo Producing Company <input checked="" type="checkbox"/>	8. Farm or Lease Name State 58
3. Address of Operator P.O. Box 10340 Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>24-S</u> RANGE <u>27-E</u> NMPM.	10. Field and Pool, or WHdcat Und. E. Black River-Atok
11. Elevation (Show whether DF, RT, GR, etc.) 3224.9 GR 3253.9 KB	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐  
PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER Recomplete to Brushy Canyon ☒  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

9/28/84 - PBDT 11,295', 10# BW, POH tbg & pkr. Set 5" 18# CIBP @ 11,100' & cap w/10 sxs C1 H cmt. RIH 7 5/8" CIBP on 2 3/8" tbg & set @ 8680'.  
9/29/84 - PBDT 8680', 10# BW. Ran cement bond log 5700'-3700'. Ran 7 5/8" CIBP set @ 5714' & capped w/15 sxs C1 H cmt to 5640'.  
9/30/84 - PBDT 5640', 10# BW. Perforated 5252'-5265' (14 shots) w/4" csg gun 1 shot/ft. Swabb dry. Acidized perfs w/2000 gals 7 1/2% NEFE acid + 21 RCNB. Avg 5 1/2 BPM @ 3200# TP. ISDP 500#, 15 min 400#. Flowed & swabbed 57 BAW. FL 4500' FS, Short 28 BLW.  
10/2/84 - Perfs 5252'-5265'. 36 Hr SITP 500#. FL 1200' FS. Swabbed 18 BLW & swabbed dry. Perforated 5138', 39', 40', 44', 45' & 46' (6 shots), 5150'-61' (12 shots), 5176', 77' & 78' (3 shots), 5182'-90' (9 shots) 5196', 97', & 98' (3 shots), 5201'-5205' (6 shots) (total 39 shots) w/4" csg gun. RIH tbg & pkr to 5007'. Swabbed 17 BLW, swabbed dry.

See attached sheet

Post ID-2  
1-11-85  
PVA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Division Operations Manager DATE 12/26/84  
APPROVED BY [Signature] TITLE Geologist DATE 2-22-85  
CONDITIONS OF APPROVAL, IF ANY: