

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES DELIVERED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2988
SANTA FE, NEW MEXICO 87501

Form O-101
Revised 12-1-81

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVALUATE EXISTING WELLS.

RECEIVED

WELL ☒ NEW ☐ C.A. ☐ OTHER ☐
Name of Operator

JAN 11 1982

DINERO OPERATING COMPANY ✓
Address of Operator

O. C. D.
ARTESIA OFFICE

RAY HOWARD

1-Y

POST OFFICE DRAWER 10505, MIDLAND, TEXAS 79702
Name of Well

Und.
S. Culebra Bluff-
Bone Spring

Well Letter P 660 FEET FROM THE South LINE AND 610 FEET FROM

East LINE, SECTION 25 TOWNSHIP 23-S RANGE 28-E

15. Elevation (Show whether D.F., R.F., etc.)

2964.7 G.L.

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

REPAIRS/REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

ADDITIONAL WORK ☐
CONFIDENTIALITY ☐
CASING TEST AND ELEMENTS ☒
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDON ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of start and completion. SEE HOLE LOGS.)

Drill 7 7/8 hole to 6960' T.D.

Circ. hole, pull out for Dresser to Log. Gamma-Ray Neutron, Formation Dens., Dual Laterlog.

Go in hole to condition mud and lay down pipe. Ran 7007.00' of 4 1/2 10.5# casing set at 6,690'.

Cement by Halliburton: 375 sx. 50/50 Poz-Mix CL. C., 400 sx. CL. H.

Plug down at 11:25 A.M. on 11/16/81

Released pressure and float held O.K. Remove BOP and set slips on pipe.

Cut off-nipole down-release rig.

Temp survey shows cement came to 5100' outside.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Sam DeNoman

Production Clerk

DATE 1-6-82

REVIEWED BY *Mike Williams*

OIL AND GAS INSPECTOR

DATE JAN 12 1982

QUESTIONS OF APPROVAL, IF ANY: