

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.
--

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Coquina Oil Corporation ✓

3. Address of Operator
P. O. Drawer 2960, Midland, Texas 79702

4. Location of Well
UNIT LETTER C 990 FEET FROM THE North LINE AND 2270 FEET FROM
THE West LINE, SECTION 21 TOWNSHIP 22S RANGE 27E N.M.P.M.

7. Unit Agreement Name
--

8. Farm or Lease Name
Nichols

9. Well No.
1

10. (Indicate Pool, or Wildcat)
Undesignated

15. Elevation (Show whether DF, RT, GR, etc.)
3111' GL

12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER Perforations & Testing ☒
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perf Morrow w/4" select fire casing gun as follows: 11,846,844', 834', 832', 830', 828', 826', 824', 815', 813', 811', 806', 796', 784', 782', 780', 778', 776', 768', 766', 764', 762', 760', 758', 573', 546', 544', 542', 540', 538', 536', 534', 499', 497', 488', 486', 484', 480', 478', 476', 474' (41 shots per foot). Set packer @ 11,395' on wireline. Test Morrow Zone. CAOF 18,803 MCFPD. Set blanking plug at 11,374'. Test plug to 1000 psi for 30 minutes, o.k.
Perf Strawn with 1-11/16" cased jet gun as follows: 10,410', 412', 414', 416', 418', 420', 422', 424', 426', 428', 430', 432', 434', 436', 438', 440', 442' (17 holes). Test well. Set RBP 10,400'. Dump 15' sand on RBP. Test to 1000 psi for 30 minutes, o.k.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Billy M. Priole

TITLE Operations Superintendent

DATE 8/11/82

APPROVED BY Leslie A. Clement

TITLE SUPERVISOR DISTRICT II

DATE AUG 12 1982

CONDITIONS OF APPROVAL, IF ANY: