

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-467
7. Unit Agreement Name
8. Farm or Lease Name State "DS" Gas Com
9. Well No. 1
10. Field and Pool, or Wildcat Und. Wolfcamp
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

**RECEIVED**  
**APR 20 1983**

1. OIL ☐ GAS ☐ OTHER- PXA

2. Name of Operator  
Amoco Production Company

3. Address of Operator  
P. O. Box 68, Hobbs, New Mexico 88240

4. Location of Well  
UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM  
East 34 TOWNSHIP 23-S RANGE 27-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3171.3' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 4-8-83. Pulled tubing. Set a cast iron bridge plug at 9099' and displaced hole with mud. Spotted 35 sacks class H cement to 9095'. Pulled tubing to 2265' and spotted 25 sacks C cement. Pulled up and spotted a 10 sack plug of class C cement at surface. Erected PXA marker. Moved out service unit 4-14-83.

0+5-NMOCD,A 1-HOU 1-F. J. Nash, HOU 1-CLF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Ferman TITLE Assist. Admin. Analyst DATE 4-20-83

ORIGINAL SIGNED  
BY LARRY BROOKS  
GEOLOGIST - NMOCD

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 22 1985

NOTIONS OF APPROVAL, IF ANY:

Post FD-2  
5-13-83  
PFA