Form 9-331	NM OIL CONS. COMMISSION	Form Approved. Budget Bureau No. 42–R1424
Dec. 1973	UNITED STATES DD	5. LEASE
	DEPARTMENT OF ATHES INTERNOR88210	NM 29414-A
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME RECEIVED
SUNDR	Y NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this	s form for proposals to drill or to deepen or plug back to a different orm 9–331–C for such proposals.)	8. FARM OR LEASE NAME UCT 1 4 1982
		Ridge Federal
1. oil well	gas 🕅 other	9. WELL NO. O. C. D.
2. NAME 0	F OPERATOR	
W.AM	oncrief, Jr.	10. FIELD OR WILDCAT NAME Baldridge Canyon Morrow
	S OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
400 Metro Bldg., Midland, Texas 79701 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		AREA
helow)		section 23, T24S, R24E
	FACE: 487' FNL and 1620' FWL section 23	12. COUNTY OR PARISH 13. STATE
	PROD. INTERVAL: LL DEPTH:	Eddy New Mexico
	APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	· · · · · · · · · · · · · · · · · · ·
	, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
DEQUEST F	DR APPROVAL TO: SUBSEQUENT REPORT OF:	4639' GD, 4662'' KB
TEST WATER		
FRACTURE T		· · · · · · · · · · · · · · · · · · ·
SHOOT OR A		(NOTE: Repart results of multiple completion on zone
		charge on Form 9-330.)
MULTIPLE C		
	NES II II	
CHANGE ZO		JUN SEP 13 1982
ABANDON* (other) casi	ing test and cement job	e all pertinent defails; and give pertinent dates,
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) pipeline of	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly stat g estimated date of starting any proposed work. If well is o ed and true vertical depths for all markers and zones pertine) Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented	te all pertinent defails; and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) pipeline of Subsurface S	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly state g estimated date of starting any proposed work. If well is of ed and true vertical depths for all markers and zones pertine) Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented ested casing to 1600# for 15 minutes. H) Ran temperature survey on 9-5-82 and sing and 9350' outside casing. (measured) Operator will perforate and complete connection is made.	te all pertinent defails; and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) pipeline of Subsurface S	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly state g estimated date of starting any proposed work. If well is of ed and true vertical depths for all markers and zones pertine O Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented ested casing to 1600# for 15 minutes. He Ran temperature survey on 9-5-82 and sing and 9350' outside casing. (measured Operator will perforate and complete connection is made. Safety Valve: Manu. and Type recertify that the foregoing is true and correct Market Market Precord Tite Exploration M	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the Set @ Ft lanagebare 9-10-82
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) pipeline of Subsurface S 18. I hereby	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly states of and true vertical depths for all markers and zones pertines) Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented ested casing to 1600# for 15 minutes. How are and sing and 9350' outside casing. (measured of the states of the states of the states of the states of the state of the states of the sta	te all pertinent defails; and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the Set @Ft lanagetoateFt ffice use)
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) oipeline of Subsurface S 18. I hereby SIGNED ALLAN	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly states g estimated date of starting any proposed work. If well is of ed and true vertical depths for all markers and zones pertine Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented ested casing to 1600# for 15 minutes. H Ran temperature survey on 9-5-82 and sing and 9350' outside casing. (measured Operator will perforate and complete connection is made. Safety Valve: Manu. and Type rectify that the foregoing is true and correct ACCEPIED FOR RECORD (ORIG. SGD.) DAVID R. GLASS TILE	te all pertinent defails; and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the Set @Ft lanagetoateFt ffice use)
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) oipeline of Subsurface S 18. I hereby SIGNED ALLAN	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly stat g estimated date of starting any proposed work. If well is of and true vertical depths for all markers and zones pertine Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented ested casing to 1600# for 15 minutes. H Ran temperature survey on 9-5-82 and sing and 9350! outside casing. (measured Operator will perforate and complete connection is made. Safety Valve: Manu. and Type recrtify that the foregoing is true and correct Correct ACCEPTED FOR RECORD (ORIG. SGD.) DAVID R. GLASS	te all pertinent defails; and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the Set @Ft lanagetoateFt ffice use)
ABANDON* (other) Casi 17. DESCRII including measure (1.) casing at CFR-2. Te (2.) inside cas (3.) oipeline of Subsurface S 18. I hereby SIGNED ALLAN	ing test and cement job BE PROPOSED OR COMPLETED OPERATIONS (Clearly states g estimated date of starting any proposed work. If well is of ed and true vertical depths for all markers and zones pertine Operator set 7 joints of 13.5# and 23 T.D. of 11,120' on 9-5-82 and cemented ested casing to 1600# for 15 minutes. H Ran temperature survey on 9-5-82 and sing and 9350' outside casing. (measured Operator will perforate and complete connection is made. Safety Valve: Manu. and Type rectify that the foregoing is true and correct ACCEPIED FOR RECORD (ORIG. SGD.) DAVID R. GLASS TILE	te all pertinent defails; and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* 7 joints of 11.6# N-80 4½" LT&C w/550 sax Class "H" w/.5 of 1% leld OK. found top of cement at 11,044! from ground level). from Morrow sands after the Set @Ft lanagetoateFt ffice use)