

All BOP equipment shall be checked for proper working order on each trip. Choke manifold and lines should be flushed periodically with water. Hydraulic chokes are to be checked on each tour by driller.

Blowout preventer drills are to be held not less than twice weekly by each drilling crew. All crew members are to be familiar with BOP and choke manifold operation and their respective duties in the event of a kick.