

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br><b>30-015-24513</b>   |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br><b>LH2395</b>   |
| 7. Lease Name or Unit Agreement Name<br><b>NEW MEXICO "DM" STATE</b>                                |
| 8. Well No.<br><b>1</b>   |
| 9. Pool name or Wildcat<br><b>SULPHATE DRAW DELAWARE</b>  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br><b>3350 GR</b>                                |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|   |
|---|
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER  |
| 2. Name of Operator<br><b>J &amp; G ENTERPRISE LTD., CO.</b>  |
| 3. Address of Operator<br><b>P.O. BOX 100, ARTESIA, NM 88210</b>  |
| 4. Well Location<br>Unit Letter <b>G</b> : <b>1980</b> Feet From The <b>NORTH</b> Line and <b>1980</b> Feet From The <b>EAST</b> Line<br>Section <b>32</b> Township <b>24S</b> Range <b>27E</b> NMPM <b>EDDY</b> County<br>10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br><b>3350 GR</b> |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIH W/5-1/2" CUTTER; CUT CSG @ 1501'
2. RIH W/O.E. TBG; SPOT 25 SXS PLUG W/2X CALC. @ 1550'- 1450'; WOC & TAG @ 1429'
3. SPOT 30 SXS PLUG W/2X CALC. @ 660'- 560'; WOC & TAG @ 538'
4. SPOT 20 SXS PLUG @ 60'- SURF.
5. INSTALL DRY HOLE MARKER

RECEIVED

MAY 18 1997

Part ID-2  
5-23-97  
PVA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc L. Neatherlin TITLE P & A SUPERVISOR DATE 4/14/97

TYPE OR PRINT NAME MARC L. NEATHERLIN TELEPHONE NO. 505-392-6969

(This space for State Use)

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE 5-12-97

CONDITIONS OF APPROVAL, IF ANY: