

13. RDMO

14. Clean location.

#) A list of materials left on location, as well as transfers for material removed from the location should be forwarded to Materials Management in Midland.

RWG
RWG

1/25/88

BRB
BRB

1/25

M. C. Welbon
Division Operations Superintendent