30-015-24603

NO. OF COPIES RECEIVED										
DISTRIBUTION			NEW	MEXICO OIL COM	SERVATION CO	MMISSION	-	orm C-101		
SANTA FE	100							evised 1-1-6		
FILE	V	V						_	Type of Leas	e
U.S.G.S.	2							STATE		
LAND OFFICE	V							5. State Oil	& Gas Lease N	No.
OPERATOR	V									*******
								//////		
APPLIC	OITAC	I FOI	R PERMIT TO	DRILL, DEEPE	N, OR PLUG B.	ACK	8			
1a. Type of Work								7. Unit Agre	ement Name	
DRIL b. Type of Well	LXX			DEEPEN		PLUG B	аск 🗌 👇	8, Farm or L	ease Name	
1	L XX		OTHER		ZONE	MULT		Neeley		
2. Name of Operator								9. Well No.		
Santa Fe Energ	gy Con	npang	y V					1		
3. Address of Operator								10. Field on	d Pool, or Wild ignated bad Morro	icat South
7200 I-40 West							M	Carls	bad Morro	DW DW
4. Location of Well			A 100	ATED 990	FEET FROM THE	north	LINE	<u>IIIII</u>	<u>IIIIII</u>	<u> </u>
UNI	I LETTE	•	000				R	//////		///////
AND 990 FEE	TFROM	THE	east LIN	IE OF SEC. 28	TWP. 225	RGE. 27		111117		
	IIII	111	11111111	<u>IIIIIIIII</u>	MMMM	<u>((((((</u>		12. County		
	////	////						Eddy		
	IIII									
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	<i>+++++</i>	<i>HH</i>	<i>+++++++++</i> +	+++++++++++++++++++++++++++++++++++++++	19. Proposed De	epth 19	A. Formation		20. Rotary or	С.Т.
	/////	////			12,200'		Morrow		Rota	M 1 T
21. Elevations (Show whe	ther DF	RT etc	\sim 21A Kind	& Status Plug. Bond		ontractor	Morrow		Date Work wi	
27.17 T		,		et, Current				September 15, 1983		
23.							¥			,
			Р	ROPOSED CASING	AND CEMENT PRO	DGRAM				
·				·····						

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
17 1/2	13 3/8	48	600	375	Circulated
12 1/4	9.5/8	36	5325	900	<u>Circulated</u>
7 7/8	5 1/2	20	12,200	1500	500' above top
	1	ł			of possible
					producing zone

Drill a 26" hole with rathole machine. Run and cement 40' of 20" conductor. Move in and rig up rotary tools. Drill a 17 1/2" hole to 600' with fresh water spud mud. Run, set and cement 13 3/8" casing. WOC 12 hours (compressive strength of cement to be 500 psi or greater). Install casinghead and nipple up BOP stack with choke manifold. Test BOP and casing to 600 psi. Drill 12 1/4" hole to 5325' with brine. Run open hole logs from TD to 2000'. Run, set and cement 9 5/8" casing. WOC 12 hours (compressive strength of cement to be 500 psi or greater). Test BOP and choke manifold to 5000 psi. Test spherical preventer to 2500 psi. Test casing to 2500 psi. Drill shoe and test casing seat to 14 ppg MWE. Drill 7 7/8" hole to 11,860' allowing hole conditions to dictate mud properties. Run DST's and core as indicated by samples and shows. Run open hole logs from TD to 5325'. Run, set and cement 5 1/2" casing. APPROVAL VALID FOR APPRO

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUC-TIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed <u>III is the set</u>	the the	Title	The for the start of the	Date	<u> </u>
(This space	e for State Use)		OIL AND GAS INSPECTOR	N. D AT DAT	SEP 2 0 1983
CONDITIONS OF APPROVA	L, IF ANY:			W W	
NSI-1730	Haur - 9-11-23		\$1.D	d'	