a

CHARLES B. READ

NORMAN L. STEVENS, JR. Vice-president

Read & Stevens. Inc.

Oil Producers P. O. Bur 1518 Reswell, New Mexico 88201 November 11, 1983

Mobil Production P.O. Box 633 Wall Towers West Midland, TX 79702

> Re: Non-Standard Location #1 Otis "34" 1828.5' FNL & 1980' FWL Sec. 34-228-27E Eddy Co., NM

Dear Sirs:

Read and Stevens, Inc. has proposed the drilling of the #1 Otis "34", on the W/2 portion unit at a non-standard location, located 1828.5' FNL and 1980' FWL of Sec.34-22S-27E. As per Oil Conservation Division Rule 104 all offsetting operators must be notified of the unorthodox location. If no objections are entered within twenty days the application will be approved.

If I can answer any questions concerning this location, please call.

Sincerely, READ & STEVENS, INC. Bruce Stubbs

Drilling & Production Manager

BS:tb