

CHARLES B. READ
PRESIDENT

NORMAN L. STEVENS, JR.
VICE-PRESIDENT

Read & Stevens, Inc.

Oil Producers

P. O. Box 1518

Roswell, New Mexico 88201

November 11, 1983

Duane Magee & Co.
314 Lorraine Ctr.
601 N. Lorraine
Midland, TX 79701

Re: Non-Standard Location
#1 Otis "34"
1828.5' FNL & 1980' FWL
Sec. 34-22S-27E
Eddy Co., NM

Dear Sirs:

Read and Stevens, Inc. has proposed the drilling of the #1 Otis "34", on the W/2 portion unit at a non-standard location, located 1828.5' FNL and 1980' FWL of Sec. 34-22S-27E. As per Oil Conservation Division Rule 104 all offsetting operators must be notified of the unorthodox location. If no objections are entered within twenty days the application will be approved.

If I can answer any questions concerning this location, please call.

Sincerely,

READ & STEVENS, INC.

Bruce Stubbs

Bruce Stubbs

Drilling & Production Manager

BS:tb