Form 9-331 NM OIL CONS. COM	M- 91000 STATES	SUBMIT DE ICATE	Form approved	/5/- 1. 1 No. 42-R1424.
Drawer DEFPART	M. NT OF THE HNTERT	PRiversising	5. LEASE DESIGNATION	
Artesia, MM 832	NM-19601			
SUNDRY NOT (Do not use this form for propo Use "APPLIC	ICES AND REPORTSMA sals to drill or to deeper or plug by ATION FOR PERMIT-" or such pr	oper to a different recommender	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
1. UIL GAS X OTHER	/ A	RTESIA, OFFICE	7. UNIT AGREEMENT NAM	1 E
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Jake L. Hamon (Phone 915-682-5218)			Union 35 Federal	
3. ADDRESS OF OPERATOR			9. WELL NO.	
611 Petroleum Build	ling, Midland, Texas	79701	10. FIELD AND POOL, OR	WHI INCOM
See also space 17 below.) At surface	FWL of Sec. 35 (SW,	·	Dublin, Ranch Dublin, Ranch 11. SEC., T., R., M., OR B SURVET OR AREA	<del>Atoka (Ext</del> ) Morrow(Ext)
			35-22S 28E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH	
	3064.1' Gr.		Eddy	New Mexico
16. Check A	ppropriate Box To Indicate N	lature of Notice, Report, or C	Other Data	
NOTICE OF INTE	NTION TO:	SUBSEQ	UENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Run Int.Csg (Note: Report results Completion or Recomp	REPAIRING W ALTERING CA ABANDONMEN & Yellow Jacket of multiple completion letion Report and Log for	et Te st X
<ol> <li>Ran electric log</li> <li>Set 7", 23# &amp; 26# cemented in 3 sta</li> <li>Re-installed 11" Note: BOP test r</li> <li>After 21 hours WO with no pressure</li> <li>Drilled Lower DV</li> <li>Drilled float col</li> <li>Ran Cement Bond L</li> <li>Drilled 7' of for (9.8# mud + 1550#</li> </ol>	, N-80, S-95, & P-110 ges with 2100 sx ceme 5000 BOPs & tested sa esults to be mailed b C, drilled upper D.V. loss. Tool and tested with lar, shoe and cement. og. mation and pressure t ) for 30 minutes with d from hole with 11.5	, LTC and Buttress cant 1-25-84. me to rated W.P. of Y y Yellow Jacket. tool and tested with 1500# for 1/2 hour wi ested casing shoe to no pressure loss.	Zellow Jacket 1 1 1500# for 1/2 th no pressure.	-27-84 2 hour loss.
	FOR RECORD TITLE	Drilling Foreman		-84
(This space for Federal or State of APPROVED BY CONDUTIONS OF APPROVED BY	TITLE		DATE	
APPROVED BY CONDITIONS OF APPROVMAYE	TITLE		DATE	

Carlebal, NEW MEXICO \*See Instructions on Reverse Side